

# **Intel® 300 Series Chipset Family On- Package Platform Controller Hub (PCH)**

**Specification Update**

---

***February 2020***

***Revision 008***



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at [intel.com](http://intel.com).

Intel technologies may require enabled hardware, specific software, or services activation. Check with your system manufacturer or retailer.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.


All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or visit [www.intel.com/design/literature.htm](http://www.intel.com/design/literature.htm).

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others.

© Intel Corporation



# Contents

---

<b>Preface</b> .....	5
<b>Summary Tables of Changes</b> .....	6
<b>Errata</b> .....	8
<b>Specification Changes</b> .....	13


§ §



# Revision History

Revision	Description	Date
001	<ul style="list-style-type: none"> <li>Initial Release</li> </ul>	September 2018
002	<ul style="list-style-type: none"> <li>The following errata are added:               <ul style="list-style-type: none"> <li>eMMC* / eMMC* or eMMC HS400 or eMMC or eMMC HS200 or HS400 or LPC Turn-Around Cycle Droop</li> <li>Intel® Trace Hub Pipe Line Empty</li> </ul> </li> </ul>	November 2018
003	<ul style="list-style-type: none"> <li>Updated xHCI Minor Revision Value</li> <li>The following errata are added:               <ul style="list-style-type: none"> <li>SD_VDD1_PWR_EN# Is Always Asserted</li> <li>SPI SFDP Program Suspend And Program Resume Instruction Fields Not Used</li> <li>PCIe Root Port CLKREQ# Asserted Low To Clock Active Timing</li> </ul> </li> </ul>	January 2019
004	<ul style="list-style-type: none"> <li>The following erratum is added:               <ul style="list-style-type: none"> <li>CLKOUT_LPC[1:0] t157 Violation With CLKRUN# Enabled</li> </ul> </li> </ul>	March 2019
005	<ul style="list-style-type: none"> <li>The following errata is added:               <ul style="list-style-type: none"> <li>xHCI USB 2.0 ISOCH Device Missed Service Interval</li> <li>xHCI Link Protocol Field Value</li> </ul> </li> </ul>	August 2019
006	<ul style="list-style-type: none"> <li>Removed erratum 1.</li> </ul>	September 2019
007	<ul style="list-style-type: none"> <li>The following errata are added:               <ul style="list-style-type: none"> <li>xHCI Short Packet Event Using Non-Event Data TRB</li> <li>eSPI SBLCL Register Bit Not Cleared by PLTRST#Specification Changes</li> </ul> </li> </ul>	November 2019
008	<ul style="list-style-type: none"> <li>The following errata are added:               <ul style="list-style-type: none"> <li>USB DbC or Device Mode Port When Resuming from S3, S4, S5, or G3 State</li> <li>xHCI Power Management Link Timer</li> <li>DbC (Debug Capability) Device Fails to Enumerate When Connected to USB 3.2 Gen 2x1 Port</li> <li>xHCI Protocol Speed ID Count Field</li> <li>System May Hang With USB-C* Power Adapter</li> </ul> </li> </ul>	February 2020

§ §



## Preface

---

This document is an update to the specifications contained in the Affected Documents table below. This document is a compilation of device and documentation errata and specification changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

### Affected Documents

Title	Document Number
Intel® 300 Series Chipset Families On-Package Platform Controller Hub Datasheet	337867 (Vol1) 337868 (Vol2)

### Nomenclature

**Errata** are design defects or errors. Errata may cause the behavior of the PCH to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present in all devices.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

§ §



## Summary Tables of Changes

---

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the product. Intel may fix some of the errata in a future stepping of the component and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

### Codes Used in Summary Tables

#### Stepping

X:	Erratum exists in the stepping indicated. Specification Change that applies to the stepping indicated.
(No mark) or (Blank box):	This erratum is fixed or not applicable in listed stepping or Specification Change does not apply to listed stepping.

#### Status

Doc:	Document change or update will be implemented.
Plan Fix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed.
No Fix:	There are no plans to fix this erratum.




## Errata

Erratum Number	Stepping	Status	Errata
	D0		
1		N/A	N/A. Erratum has been removed.
2	X	No Plan to Fix	xHCI Host Controller Reset May Cause A System Hang
3	X	No Plan to Fix	Intermittent CATERR May Occur When Back To Back xHCI Host Controller Resets Are Performed
4	X	No Plan to Fix	USB DbC Or Device Mode Port When Resuming From S3, S4, S5, Or G3 State
5	X	No Plan to Fix	xHCI Minor Revision Value
6	X	No Plan to Fix	xHCI Link Error Count Field
7	X	No Plan to Fix	xHCI U1 Exit LFPS Duration
8	X	No Plan to Fix	xHCI Power Management Link Timer
9	X	No Plan to Fix	SUSPWRDNACK Not Driven High When Intel® CSME Is Power Gated
10	X	No Plan to Fix	DbC (Debug Capability) Device Fails To Enumerate When Connected To USB 3.1 Gen 2 Port
11	X	No Plan to Fix	SDXC CRC Detection
12	X	No Plan to Fix	eMMC* / eMMC* or eMMC HS400 or eMMC or eMMC HS200 or HS400 or LPC Turn-Around Cycle Droop
13	X	No Plan to Fix	Intel® Trace Hub Pipe Line Empty
14	X	No Plan to Fix	SD_VDD1_PWR_EN# Is Always Asserted
15	X	No Plan to Fix	SPI SFDP Program Suspend And Program Resume Instruction Fields Not Used
16	X	No Plan to Fix	PCIe Root Port CLKREQ# Asserted Low To Clock Active Timing
17	X	No Plan to Fix	CLKOUT_LPC[1:0] t157 Violation With CLKRUN# Enabled
18	X	No Plan to Fix	xHCI USB 2.0 ISOCH Device Missed Service Interval
19	X	No Plan to Fix	xHCI Link Protocol Field Value
20	X	No Plan to Fix	USB DbC or Device Mode Port When Resuming from S3, S4, S5, or G3 State
21	X	No Plan to Fix	xHCI Power Management Link Timer
22	X	No Plan to Fix	DbC (Debug Capability) Device Fails to Enumerate When Connected to USB 3.2 Gen 2x1 Port
23	X	No Plan to Fix	xHCI Protocol Speed ID Count Field
24	X	No Plan to Fix	System May Hang With USB-C* Power Adapter

## Specification Changes

Number	Stepping	Specification Changes
	D0	
		No specification changes in this revision of the Specification Update

§ §



## Errata

---

### 1. N/A. Erratum has been removed.

### 2. xHCI Host Controller Reset May Cause A System Hang

**Problem:** xHCI Host Controller may not respond following system software setting (Bit 1 = '1') the Host Controller Reset (HCRST) of the USB Command Register (xHCIBAR + 80h).

**Implication:** CATERR may occur resulting in a system hang.

**Workaround:** A 1ms delay is necessary anytime following System Software setting (Bit 1 = '1') Host Controller Reset (HCRST) of the USB Command Register (xHCIBAR + 80h).

**Status:** No Plan To Fix.

### 3. Intermittent CATERR May Occur When Back To Back xHCI Host Controller Resets Are Performed

**Problem:** The xHCI host controller may fail to respond, due to an internal race condition, if consecutive Host Controller resets are performed.

**Implication:** A processor CATERR may occur during warm boot testing or S4/S5 cycling tests.

**Workaround:** Software should add a 120 ms delay in between consecutive host controller resets.

**Status:** No Plan to Fix.

### 4. USB DbC Or Device Mode Port When Resuming From S3, S4, S5, Or G3 State

**Problem:** If a PCH USB Type-C\* port is configured in Device Mode (or in DbC mode) and connected to an external USB 3.1 host controller, it may cause the USB port to go into a non-functional state in the following scenarios:

1. The PCH resumes from S3, S4, or S5 state, the port may remain in U2.
2. The port is connected to a USB 3.1 Gen 1 host controller when resuming from S3, S4, S5, or G3, the port may enter into Compliance Mode or an inactive state if Compliance mode is disabled.
3. The port is connected to a USB 3.1 Gen 2 host controller when resuming from S3, S4, S5, or G3, the port may enter an inactive state.

**Implication:** PCH USB Type-C port configured in Device Mode (or in DbC mode) may fail to enumerate or become unavailable.

**Workaround:** None.

**Status:** No Plan to Fix.

### 5. xHCI Minor Revision Value

**Problem:** The PCH reports USB Minor Revision in the XECP\_SUPP\_USB3\_0 register (offset 8020h) as 01h. The USB-IF released a ECN to update the minor revision to 0x10h.

**Implication:** USB-IF xHCI CV TD 1.5 may report a failure. Intel has obtained a waiver for TD 1.5.

**Note:** No functional impact is expected.

**Workaround:** None.


**Status:** No Plan to Fix.

### 6. xHCI Link Error Count Field

**Problem:** The xHCI Link Error Count Field in the USB 3.0 Port X Link Info – (PORTLI) register is implemented as Read/Write instead of Read Only as defined by the xHCI specification.

**Implication:** USB-IF xHCI CV TD 3.17 may report a failure. Intel has obtained a waiver for TD 3.17.





*Note:* No functional impact is expected.

Workaround: None.

Status: No Plan to Fix.

### **7. xHCI U1 Exit LFPS Duration**

**Problem:** The xHCI U1 Exit LFPS (t13-t11) duration timing is implemented as 0.6 us to 0.9 us. The USB-IF released a ECN updating this timing value to 0.9 us to 1.2 us.

**Implication:** USB-IF xHCI CV TD 7.18 may report a failure. Intel has obtained a waiver for TD 7.18.

*Note:* No functional issues are expected.

Workaround: None.

Status: No Plan to Fix.

### **8. xHCI Power Management Link Timer**

**Problem:** The xHCI implements the Power Management Link Timer (PM LC Timer) Timeout value as 10 us instead of 4 us as defined by the USB 3.1 specification.

**Implication:** USB-IF xHCI CV TD 7.21 may report a failure. Intel has obtained a waiver for TD 7.21.

*Note:* No functional issues are expected.

Workaround: None.

Status: No Plan to Fix.

### **9. SUSPWRDNACK Not Driven High When Intel® CSME Is Power Gated**

**Problem:** When the platform is in Sx (S3, S4 or S5) and the Intel® CSME is in the power gated state (CM3-PG), the PCH does not drive SUSPWRDNACK as expected.

**Implication:** When the Intel® CSME is in power gated state, the PCH Primary Well will not be turned off on platforms that use SUSPWRDNACK to control the well.

*Note:* Platforms that support Deep Sx are not impacted as SUSPWRDNACK is not used.

Workaround: None.

Status: No Plan to Fix.

### **10. DbC (Debug Capability) Device Fails To Enumerate When Connected To USB 3.1 Gen 2 Port**

**Problem:** The PCH DbC (Debug Capability) Device may fail to enumerate if connected to a USB host controller's USB 3.1 Gen 2 port.

**Implication:** The PCH DbC may not function.

Workaround: None.

Status: No Plan to Fix.

### **11. SDXC CRC Detection**

**Problem:** The PCH DbC (Debug Capability) Device may fail to enumerate if connected to a USB host controller's USB3.1 Gen 2 port.

**Implication:** The PCH DbC may not function.

Workaround: None.

Status: No Plan to Fix.



## 12. **eMMC\* / eMMC\* or eMMC HS400 or eMMC or eMMC HS200 or HS400 or LPC Turn-Around Cycle Droop**

**Problem:** During the turn-around cycle where the PCH transfers ownership of the LPC LAD[3:0] signals to another device, a race condition may occur where the PCH LPC controller may improperly disable its output buffers.

**Implication:** During this condition, the voltage on LAD[3:0] may be observed to temporarily droop to below  $V_{IH}$  min from the 1st to 2nd clock of the turnaround cycle. There are no known functional failures due to this issue.

**Workaround:** None.

**Status:** No Plan to Fix.

## 13. **Intel® Trace Hub Pipe Line Empty**

**Problem:** The Intel® Trace Hub Pipe Line Empty bit (CSR\_MTB\_BAR, Offset D4h) for a given output port may be set while the Input Buffer Empty for the associated output port is not set. This will only happen when the captureDone signal is de-asserted by clearing the ForceCaptureDone bit (CSR\_MTB\_BAR, Offset D8h) is cleared or the StoreQual[0] signal is de-asserted by the Trigger Unit before the pipe line is empty, and the destination is either system memory or USB (DCI).

**Implication:** There may be valid trace data in the trace source input buffer which did not get sent to the destination (output port).

**Workaround:** None. CaptureDone should be cleared or de-asserted after the pipe line is empty.

**Status:** No Plan to Fix.

## 14. **SD\_VDD1\_PWR\_EN# Is Always Asserted**

**Problem:** SD\_VDD1\_PWR\_EN# does not de-assert during SDXC D3 or when SD card is not inserted.

**Implication:** For platforms using SD\_VDD1\_PWR\_EN#, the SDXC card connector is always powered and may impact system power.

**Workaround:** A BIOS code change has been identified and may be implemented as a workaround for this erratum.

**Status:** No Plan to Fix.

## 15. **SPI SFDP Program Suspend And Program Resume Instruction Fields Not Used**

**Problem:** For flash device suspend / resume opcodes, the SPI controller does not use JEDEC SFDPs 13th DWORD bits [15:0], Program Suspend Instruction and Program Resume Instruction fields. The controller only uses bits [31:16], Suspend Instruction and Resume Instruction fields, to obtain the suspend / resume opcodes.

**Implication:** If the SPI flash requires bits [15:0] to be different than bits [31:16], then the suspend / resume feature is not functional. In this case, system behavior varies depending on what the suspend / resume instruction is and when it is generated.

**Note:** Major flash vendors have been using the same value for bits [31:16] and bits [15:0].


**Workaround:** None.

If a device requires bits [15:0] to be different than bits [31:16], then disable the device suspend / resume via the SPI Suspend / Resume Enable soft strap.

**Status:** No Plan to Fix.

## 16. **PCIe Root Port CLKREQ# Asserted Low To Clock Active Timing**

**Problem:** During L1 exit, the PCH PCIe Root Ports may exceed the CLKREQ# asserted low to clock active maximum specification due to PCH PCIe clock un-gate path delays.



Implication: PCIe end point device L1 exit instabilities may be observed.

*Note:* PCIe end point devices that message LTR latency greater than or equal to 1  $\mu$ s are not affected by this.

Workaround: None.

- Platforms not supporting S0ix with PCIe end point devices that do not support LTR may disable the associated PCH SRCCLKREQ# signal to keep the PCIe clock active during L1.
- Platforms supporting S0ix with PCIe end point devices that have LTR latencies less than 1  $\mu$ s may disable the associated PCH SRCCLKREQ# signal to keep the PCIe clock active during L1.

Status: No Plan to Fix.

### **17. CLKOUT\_LPC[1:0] t157 Violation With CLKRUN# Enabled**

Problem: With CLKRUN# enabled, the PCH may exceed the t157 timing, LFRAME# Valid Delay from CLKOUT\_LPC[1:0] Rising.

Implication: A LPC device may not observe the initial transaction from the PCH when CLKOUT\_LPC is being re-started following the assertion of CLKRUN# by PCH.

Workaround: A Platform Firmware code change has been identified and may be implemented as a workaround for this erratum.

Status: No Plan to Fix.

### **18. xHCI USB 2.0 ISOCH Device Missed Service Interval**

Problem: When the xHCI controller is stressed with concurrent traffic across multiple USB ports, the xHCI controller may fail to service USB 2.0 Isochronous IN endpoints within the required service interval.

Implication: USB 2.0 isochronous devices connected to the xHCI controller may experience dropped packets.

*Note:* This issue has only been observed in a synthetic environment.

Workaround: None.

Status: No Plan to Fix.

### **19. xHCI Link Protocol Field Value**

Problem: The xHCI Host Controller reports the Link Protocol (LP) bits [15:14] as 0x0h in the XECP\_SUPP\_USB3\_5 Super Speed Plus register (xHCI MMIO offset 8034h). The xHCI spec rev 1.1 (published in Nov. 2017) defines this bit should be set to 0x1h for SuperSpeed USB 10 Gbps port.

Implication: USB-IF xHCI CV TD 1.9 may report a failure. The failure was not observed during the USB certification for the xHCI USB host controller and thus a waiver was not required.

*Note:* No functional impact is expected.

Workaround: None.

Status: No Plan to Fix.

### **20. USB DbC or Device Mode Port When Resuming from S3, S4, S5, or G3 State**

Problem: If a PCH USB Type-C\* port is configured in Device Mode (or in DbC mode) and connected to an external USB 3.2 host controller, it may cause the USB port to go into a non-functional state in the following scenarios: 1)The PCH resumes from S3, S4, or S5 state, the port may remain in U2. 2)The port is connected to a USB 3.2 Gen 1x1



host controller when resuming from S3, S4, S5, or G3, the port may enter into Compliance Mode or an inactive state if Compliance Mode is disabled. 3)The port is connected to a USB 3.2 Gen 2x1 host controller when resuming from S3, S4, S5, or G3, the port may enter an inactive state.

Implication: PCH USB Type-C\* port configured in Device Mode (or in DbC mode) may fail to enumerate or become unavailable.

Workaround: None identified.

Status: No Plan to Fix.

## **21. xHCI Power Management Link Timer**

Problem: The xHCI implements the Power Management Link Timer (PM LC Timer) Timeout value as 10 us instead of 4 us as defined by the USB 3.2 specification.

Implication: USB-IF xHCI CV TD 7.21 may report a failure. Intel has obtained a waiver for TD 7.21. Note: No functional issues are expected.

Workaround: None identified.

Status: No Plan to Fix.

## **22. DbC (Debug Capability) Device Fails to Enumerate When Connected to USB 3.2 Gen 2x1 Port**

Problem: The PCH DbC (Debug Capability) Device may fail to enumerate if connected to a USB host controller's USB 3.2 Gen 2x1 port.

Implication: The PCH DbC may not function.

Workaround: None identified.

Status: No Plan to Fix.

## **23. xHCI Protocol Speed ID Count Field**

Problem: The xHCI Host Controller reports an incorrect Protocol Speed ID Count value for the USB 3.2 Supported Protocol Capability register - xHCI MMIO offset 8028 bits [31:28].

Implication: USB-IF xHCI CV TD 1.9 may report a failure. Note: No functional impact is expected.

Workaround: None identified.

Status: No plan to Fix.

## **24. System May Hang With USB-C\* Power Adapter**

Problem: Connecting a USB-C\* power adapter to a PCH USB port may cause a race condition that can result in a xHCI controller hang. This issue only occurs on designs where the USB-C Power Delivery (PD) implements OOB messaging to communicate with the PCH for port mapping.

Implication: The system may hang. Note: This issue does not occur when the system is in Sx state and has only been observed when repeatedly connecting a USB-C power adapter.

Workaround: None identified.

Status: No plan to Fix.



## **Specification Changes**

---

There are no Specification Changes in this revision of the Specification Update.

**§ §**